



Unidirectional dimensions are placed so they can be read from the bottom of the drawing sheet. This method is commonly used in mechanical drawing.